# Weathertzatton Assistance Program

# Work Order (Bid Form)

## **WORK ORDER INFORMATION**

Work Order Name: WO/20002BR0167/1Work Order Type: WeatherizationAudit Name: 20002BR0167 Audit

#### **CLIENT INFORMATION**

Client Name: Address:
Client ID: 20002BR0167

Alt. Client ID: Bradley

## **AGENCY INFORMATION**

Agency:Bradley-Cleveland CSAAgency Phone:

Address: P. O. Box 3297 Fax:
Cleveland, TN 37320 Email Address:

Agency Contact: Godwin, Keith Work Phone:

Cell Phone: (865) 437-7772

Email Address: godwin.wx@bellsouth.net

Company Name & License Number:	
Contractor's Signature:	

# **COMMENT**

Measure 1 Infiltration Redctn			Components						Inspected	
C	2. Sea 3. Sea 4. Foa Garage 5. Mas	nent 1. Seal plumbing at Kit & Water heater 2. Seal at electric box 3. Seal and add 1/4 round trim (5 ft) behind commode. 4. Foam and trim to gaps in ceiling in Dining room connecting Kitch Garage. Mostly around center beam (24 ft) 5. Mastic 8 boots (5-7 pa). Seal disconnected supply line going to t Dining room vent (21pa).								
					Estimated		-	Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
0	Miscellaneous Supplies	Infiltration Reduction	Each	1						
(	Other Detail						] [			
							] []			
				Measur	e Sub Total:		] .	Sub Total:		
	Field Notes:									
	Measure 2 Use	er-Spec Ceiling R old porch with shed-roof.	Owner late		<i>Componen</i> ed Pitched ro		op.		Inspected	
	Measure 2 Use		Owner late		•	oof over-t	op.	Actual	Inspected	
C	Measure 2 Use	old porch with shed-roof.	Owner late		ed Pitched ro	oof over-t	op.		Inspected Total	
<i>C</i>	Measure 2 Use Comment A-2 is o	old porch with shed-roof. sulation on old roof.		er adde	ed Pitched ro	oof over-t		Actual		
# 1	Measure 2 Use Comment A-2 is o Blow in Material / Labor	old porch with shed-roof. sulation on old roof.  Description / Comment  Attic Insulation - Blown	Units	er adde	ed Pitched ro	oof over-t		Actual		
# 1	Measure 2 Use Comment A-2 is o Blow in Material / Labor Insulation	old porch with shed-roof. sulation on old roof.  Description / Comment  Attic Insulation - Blown	Units	er adde	ed Pitched ro	oof over-t		Actual		
<b>C</b> #	Measure 2 Use Comment A-2 is o Blow in Material / Labor Insulation	old porch with shed-roof. sulation on old roof.  Description / Comment  Attic Insulation - Blown	Units SqFt	Qty 288	ed Pitched ro	oof over-t	Qty	Actual		

Client Name: Client ID: 20002BR0167 Alt. Client ID: Bradley

Measure 3 L	Jser-Spec Ceiling R			Componen	ts A1		ı	Inspected
<b>Comment</b> Repl	ace attic access in closet. (b	olock & ins	ulate)					
				Estimated		Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Attic Insulation - Blown Cellulose - R-30	SqFt	864					
2 Miscellaneous Supplies	Added Misc Cost - Blown Cellulose - R-30	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
	Vindow Sealing  k int all windows.			Componen	ts WD1, D4,5,6		9,10,W	Inspected
				Estimated			Actual	
# Material / Labor	r Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Windows	Window Sealing	Each Window	10					
	Caulking Interior / Exterior							
2 Labor	Window Sealing	Each Window	10					
Other Detail						1		
			Measur	e Sub Total:		] ;	Sub Total:	
Field Notes:								

Measure 5	DWH Pipe Insulation			Componer	nts			Inspected	
Comment In	bathroom, sealed in closet.								
				Estimated	<i>d</i>	Actual			
# Material / La	bor Description / Comment	t Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Insulation	DHW Pipe Insulation	Each	1						
	cost for 10' of wrap								
2 Labor	DHW Pipe Insulation	Each	1						
Other Detail									
			Measur	e Sub Total:		] ;	Sub Total:		
Measure 6 Comment Ex	Digital Thermostat (ea) kisting Mercury style in poor	condition.		Componer Estimated			Actual	Inspected	
# Material / La	bor Description / Comment	t Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
Heating Equipment	bor Description/Comment	Each	1		TOTAL	Qiy	Onit Cost	Total	
Other Detail		_							
			Measur	e Sub Total:		] ;	Sub Total:		
Field Notes:									

	leasure 7 Fix Improper Venting of Bathroom Exhaust Fan			Componen			Inspected	
Comment Vent EXISTING Fan to the Exterior Gable				stiff piping (1 <i>Estimated</i>				
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety     Items	Equipment	Each	1					
	use dryer vent price							
2 Labor	Labor	Hour	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
	III Kitchen Exhaust Fan Exterior. Either thru exte			Componen attic (roof or	gable). R	emove		Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety     Items	Kitchen exhaust fan	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

Measure 9 Vapor Barrier Needed (Basement/Crawlspace) = 864 SF				Componen	1	Inspected			
Comment Cannot access all areas due to clearance.									
					Estimated	<u>'</u>		Actual	
# Material / La	bor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Unspecified	I	Basement / crawlspace vapor barrier (+)	Each	864					
Other Detail							1		
				Measur	e Sub Total:		] ;	Sub Total:	
Field Notes:									
			Work Or	der Gra	and Total:		Gran	d Total:	